



| KORRUPTIE RUIMDE EKSPLIKATISIOEN |             |      |
|----------------------------------|-------------|------|
| NR NIMI                          | PINDALA     |      |
| KORTER 98                        | 47 100.4 m2 |      |
| 98-1 Esak                        |             | 5.3  |
| 98-2 Kõndor                      |             | 3.0  |
| 98-3 Elutuba/aok                 |             | 36.8 |
| 98-4 WC                          |             | 3.6  |
| 98-5 Magistuba                   |             | 12.3 |
| 98-6 Magistuba                   |             | 12.6 |
| 98-7 Duširuum                    |             | 1.7  |
| 98-8 Saun                        |             | 7.2  |
| 98-9 Abi                         |             | 1.4  |
| 98-10 Magistuba                  |             | 12.7 |
| 98-11 Rõdu                       |             | 8.6  |
| 98-12 Terrass                    |             | 4.2  |
| KORTER 99                        | 17 20.7 m2  |      |
| 99-1 Esak                        |             | 2.5  |
| 99-2 Elutuba/aok                 |             | 16.7 |
| 99-3 Duširuum                    |             | 2.5  |
| 99-4 Terrass                     |             | 9.6  |
| KORTER 100                       | 3T 61.1 m2  |      |
| 100-1 Esak                       |             | 3.5  |
| 100-2 Kõndor                     |             | 3.1  |
| 100-3 Elutuba/aok                |             | 23.9 |
| 100-4 WC                         |             | 1.2  |
| 100-5 Pannipaik                  |             | 10.1 |
| 100-6 Duširuum                   |             | 2.2  |
| 100-7 Magistuba                  |             | 10.2 |
| 100-8 Magistuba                  |             | 10.6 |
| 100-9 Terrass                    |             | 9.8  |

[illegible]

Avenida Barboise P.O. Box 00  
 reg. nr. ES-9286546 Patna int 541 1314 Tallinn  
 telefon +372 699 5625 e-post mal@plaza.ee